JUL 2 3 2019

Witness:

State of New Mexico

BRADENHEAD TEST REPORT

HOBBS Octorgy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

OCCIDENTAL PERMIAN, LTD RECEIVED Property Name NORTH HOBBS (G/SA) UNIT									30-025-43841			
									Well No. 657			
					7. Surface Locat	ion						
UL - Lot B	Section 24	Township 18S	Range 37E	ļ	Feet from		S Line i	Feet From 2269	E/W Line EAST	County		
В	24	165	3/6		Well Status		11	2209	EAST	LEA		
		-1	CHIPT IN		PRODUCING			DATE				
Well Status			SHUT-IN		- Mag		2-16-19		INT/Gas			
MCI		N BRADENI		TERMED	IATE TO ATMOSPH	ERE INDI				<u> </u>		
f bradenhead			of the descripti		OBSERVED DA							
	oracement rower water		(A)Surf-Interm		(B)Interm(1)-Interm(2)		(C)Interm-Prod		rod Csng	(E)Tubing		
ressure	ressure		94				43.44		300	ام رجار		
low Chara	low Characteristics		 79		NIA		N/4		30 0	1565		
Puff		1	€ Y N		Y / N		Y / N		Ø√ N	4		
Steady Flow			Y / (%)		Y / N		Y / N		Y / 🚯	1		
Surges			Y / 🗞		Y / N		Y / N		Y / (N)			
Down to nothing			Ø N		Y/N		Y / N		⅓ / N			
Gas or Oil			⊘ / N		Y/N		Y/N		(V)/ N			
Water			Y / 👩		Y/N		Y/N		Y / 🕅			
f hradenhead	d flowed wa	ter, check all	of the descripti	ons that a	pply:							
CLEAR		FRE	_		SALTY		SULFUR		BLACK	BLACK		
Remarks:				-		IN	JECTING	AT THIS TIME	wrr,			
								~	415-2201 W	2Fd		
								,	9			
									Bryan bofilm 575-441-9739			
									7-16-19			
Signature:								OIL CONSERVATION DIVISION				
Printed name: MENDY JOHNSON								Entered into RBDMS				
Title: ADMINISTRATIVE ASSOCIATE								Re-test ///				
E-mail Addr	ess: <u>mendy</u>	johnson@ox	(y.com									
Date:			Phone: 806-	592-6280								