

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name BREITBURN OPERATING LP		API Number 30-025-45691
Property Name ENCORE M STATE		Well No. 24

1. Surface Location

UL - Lot K	Section 20	Township 22-S	Range 37-E	Feet from 1356	N/S Line S	Feet from 2316	E/W Line W	County Lea
---------------	---------------	------------------	---------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJ NO	INJECTOR NO	SWD NO	PRODUCER OIL	GAS NO	DATE 8-21-19
------------------	----------------	-----------	----------------	-----------	-----------------	-----------	-----------------

OBSERVED DATA

	(A) Surface	(B) Interval 1	(C) Interval 2	(D) Prod Casing	(E) Tubing
Pressure	160	0	N/A	53	318
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Eddie Trujillo</i>		OIL CONSERVATION DIVISION	
Printed name: Eddie Trujillo		Entered into RBDMS	
Title: Leadman		Re-test <i>JA</i>	
E-mail Address: eddie.trujillo@mavresources.com			
Date:	Phone: 575-399-3329		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM