

HOBBS OCD

OCT 28 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name DKD		API Number 30-025-27950	
Property Name VULTURE VP ST		Well No. #1	

1. Surface Location									
UL - Lot D	Section 14	Township 15S	Range 33E		Feet from 330	N/S Line N	Feet from 330	E/W Line W	County LEA

Well Status								DATE
TA'D WELL YES	☒ NO	YES	SHUT-IN ☒ NO	INJ	INJECTOR ☒ SWD	OIL	PRODUCER GAS	10-28-19

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	150
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness: Shay Robinson			

INSTRUCTIONS ON BACK OF THIS FORM