

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

OCT 28 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name DKD						API Number 30-025-34197			
Property Name WATSON 6						Well No. #1			
1 Surface Location									
UL - Lot N	Section 6	Township 16S	Range 36E	Feet from 2857	N/S Line S	Feet From 1417	E/W Line W	County LEA	
Well Status									
TA'D WELL YES ☒ NO		SHUT-IN YES ☒ NO		INJ INJ ☒ SWD		PRODUCER OIL ☒ GAS		DATE 10-28-19	

OBSERVED DATA

	(A)Surface	(B)Intern(1)	(C)Intern(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	VAC
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Ward and if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone:	
Witness: Steve Holmson		

INSTRUCTIONS ON BACK OF THIS FORM