

District I
1625 N. French
Phone: (575) 393-0720

HOBBS OCD

JUL 08 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Southwest Royalties, INC.	API Number 30-025-10256
Property Name Elliott B 13	Well No. 1

Surface Location									
UL - Lot E	Section 13	Township 22S	Range 37E	Feet from 1980	N/S Line N	Feet From 660	E/W Line W	County LEA	

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 6/13/2019	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			21	23
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Dillon Salas	OIL CONSERVATION DIVISION
Printed name: Dillon Salas	Entered into RBDMS
Title: Production Engineer	Re-test
E-mail Address: apollo.salas44@gmail.com	
Date: 6/14/2019	Phone: (575) 492-1236
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM