

Distric 1
1625 N. Fremont
Phone: (575) 771-1000

HOBBS OCD

JUL 08 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Southwest Royalties, INC.		API Number 30-025-10439	
Property Name LEE		Well No. 1	

Surface Location									
UL - Lot I	Section 23	Township 22S	Range 37E		Feet from 1980	N/S Line S	Feet From 660	E/W Line E	County LEA

Well Status								
TA'D WELL YES	NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 6/13/2019

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			14	15
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Dillon Salas</i>		OIL CONSERVATION DIVISION	
Printed name: Dillon Salas		Entered into RBDMS	
Title: Production Engineer		Re-test	
E-mail Address: apollo.salas44@gmail.com			
Date: 6/14/2019	Phone: (575) 492-1236		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM