

HOBBS OCD

OCT 21 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name DKD	API Number 30-065-20809
Property Name Grafton	Well No. #4

1. Surface Location

UL - Lot A	Section 10	Township 8S	Range 32E	Feet from 660	N/S Line N	Feet From 660	E/W Line E	County Chaves
----------------------	----------------------	-----------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	-------------------------

Well Status

TA'D WELL YES ☒ NO ☒	SHUT-IN YES ☒ NO ☒	INJ ☒	INJECTOR SWD ☒	OIL PRODUCER ☒	GAS ☒	DATE 10-21-19
---	---	---	--	--	---	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	VAC
Flow Characteristics					
Puff	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	CO2 ☒
Steady Flow	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	WTR ☒
Surges	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	GAS ☒
Down to nothing	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	
Water	Y/N ☒	Y/N ☒	Y/N ☒	Y/N ☒	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Wayne Robinson		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness: Dary Robinson			

INSTRUCTIONS ON BACK OF THIS FORM