

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

NOV 04 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corp	API Number 30-025-04156
Property Name NMBSAU	Well No. 015 (1815)

Surface Location

UL - Lot 0	Section 2	Township 20S	Range 36E	Feet from 660	N/S Line S	Feet from 1980	E/W Line E	County Lea
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 8-22-19
------------------	-----------	----------------	-----------	------------	----------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0		20	0
Flow Characteristics				Off	
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					apples

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) Down to 0 in 10 seconds (Gas)

(E) well on vacuum due to decreased water production from
Plant

Signature: Justin Solomon	OIL CONSERVATION DIVISION
Printed name: Justin Solomon	Entered into RDBMS
Title: Pumper II	Re-test
E-mail Address: Justin.Solomon@Apache Corp. Com	
Date: 8-22-19	
Phone: 575-390-4054	
Witness:	