

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

NOV 04 2019

BRADENHEAD TEST REPORT

Operator Name Apache Corp	Well No. 30-065-04165
Property Name NM65AU	Well No. 001 (1801)

2. Surface Location

UL - Lot A	Section 2	Township 20s	Range 36E	Feet from 660	N/S Line N	Feet from 660	E/W Line E	County Lea
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR ☒	SWD	PRODUCER OIL	GAS	DATE 7-12-19
---	---	--	-----	-----------------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0		0	200	0
Flow Characteristics	None		None	Blow	
Puff	YIN	YIN	YIN	YIN	CO2 ☒
Steady Flow	YIN	YIN	YIN	YIN	WTR ☒
Surges	YIN	YIN	YIN	YIN	GAS ☒
Down to nothing	YIN	YIN	YIN	YIN	Type of Fluid Injected for Waterflood if applies
Gas or Oil	YIN	YIN	YIN	YIN	
Water	YIN	YIN	YIN	YIN	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(E) well is on vacuum due to decreased water production from plant.

Signature: Justin Solomon	OIL CONSERVATION DIVISION
Printed name: Justin Solomon	Entered into RBDMS
Title: Pumper II	Re-test
E-mail Address: Justin.Solomon@ApacheCorp.Com	
Date: 7-12-19	
Phone: 575-390-4054	
Witness:	