

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

NOV 04 2019

BRADENHEAD TEST REPORT

Operator Name Apache Corp		APC 36-025-05767	
Property Name NMBSAU		Well No. 001 (150)	

1. Surface Location

UL Lot A	Section 31	Township 19E	Range 37E	Feet from 660	N/S Line N	Feet from 660	E/W Line E	County Lea
--------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 8-22-19
------------------	-----------	----------------	-----------	------------------------	-----	-----	-----------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	0		60	1080
Flow Characteristics				Flow	
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) bled Down to Ops in 20 Seconds.

Signature: Justin Solomon		OIL CONSERVATION DIVISION	
Printed name: Justin Solomon		Entered into RBDMS	
Title: Pumper II		Re-test	
E-mail Address: Justin.Solomon@ApacheCorp.Com			
Date: 8-22-19	Phone: 575-390-4054		
Witness:			