

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

NOV 04 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Apache Corp		API Number 30-025-31587	
Property Name NM65AU		Well No. 019 (1419)	

2. Surface Location

UL - Lot C	Section 36	Township 19S	Range 36E	Feet from 80.5	N/S Line N	Feet from 1505	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR NO	SWD	OIL	PRODUCER NO	GAS	DATE 7-12-19
-----	------------------------	-----	----------------------	------------	-----------------------	-----	-----	-----------------------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	0		20	740
Flow Characteristics	Puff	Puff		Puff	
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☒
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☒
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) puff Bleed to 0 10 seconds

Signature: Justin Solomon		OIL CONSERVATION DIVISION	
Printed name: Justin Solomon		Entered into RBDMS	
Title: Pumper II		Re-test	
E-mail Address: Justin.Solomon@Apache Corp. Com			
Date: 7-12-19	Phone: 575-390-4054		
Witness:			