

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

COLGATE OPERATING, LLC		Operator Name	API Number 30-025-37036
EAST SHUGART DELAWARE UNIT			Property Name Well No. 021

7. Surface Location

UL - Lot E	Section 19	Township 18-S	Range 32-E	Feet from 1425	N/S Line N	Feet From 1000	E/W Line W	County LEA
---------------	---------------	------------------	---------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR NO	PRODUCER OIL	DATE 11/20/19
------------------	----------------	----------------	-----------------	------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	1/2	1/2	0	1100
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

HOBBS OCD
NOV 20 2019
RECEIVED

Signature: <i>Sammy Licor</i>		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date: 11/20/19	Phone:	
Witness: KERRY FORTNER-OCD 575-399-3221		