

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name COLGATE OPERATING, LLC		API Number 30-025-37368
Property Name EAST SHUGART DELAWARE UNIT		Well No. 018

7. Surface Location

UL - Lot D	Section 19	Township 18-S	Range 32-E	Feet from 200	N/S Line N	Feet From 1025	E/W Line W	County LEA
----------------------	----------------------	-------------------------	----------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR NO	PRODUCER OIL	DATE 11/20/19
-------------------------	-----------------------	-----------------------	------------------------	-------------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	NA	NA	0	950
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	0/N	Y/N	Y/N	0/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

HOBBS OCD
NOV 20 2019
RECEIVED

Signature: Sammy Liu		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test XJ
E-mail Address:		
Date: 11/20/19	Phone:	
Witness: KERRY FORTNER-OCD 575-399-3221		