

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

NOV 20 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name LEGACY RESERVES OPERATING LP		API Number 30-025-10604
Property Name SKELLY PENROSE A UNIT		Well No. 39

Surface Location

UL - Lot O	Section 03	Township 23S	Range 37E	Feet from 660	N/S Line S	Feet From 1980	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJ	SWD	☒ OIL	PRODUCER GAS	DATE 11-18-19
------------------	-------------------------------------	----------------	-------------------------------------	-----	-----	--------------------------------------	-----------------	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	ϕ			ϕ	40
Flow Characteristics					
Puff	☒ Y / ☒ N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	☒ Y / ☒ N	Y / N	Y / N	Y / N	WTR ☐
Surges	☒ Y / ☒ N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	☒ Y / ☒ N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	☒ Y / ☒ N	Y / N	Y / N	Y / N	
Water	☒ Y / ☒ N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Dustin Reeder</i>		OIL CONSERVATION DIVISION	
Printed name: DUSTIN REEDER		Entered into RBDMS	
Title: PRODUCTION TECH		Re-test <i>[Signature]</i>	
E-mail Address:			
Date: 11-18-19	Phone:		
Witness:			