

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

NOV 20 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name LEGACY RESERVES OPERATING LP	API Number 30-025-10680
Property Name SKELLY PENROSE A UNIT	Well No. 58

Surface Location

UL - Lot O	Section 09	Township 23S	Range 37E		Feet from 660	N/S Line S	Feet From 1980	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL. YES	NO	SHUT-IN YES	NO	INJ NO	INJECTOR NO	SWD NO	PRODUCER OIL	GAS NO	DATE 11-18-19
--------------------------	-----------	-----------------------	-----------	------------------	-----------------------	------------------	------------------------	------------------	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	41			41	45
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Dustin Reeder	OIL CONSERVATION DIVISION
Printed name: DUSTIN REEDER	Entered into RBDMS
Title: PRODUCTION TECH	Re-test
E-mail Address:	
Date: 11-18-19	
Phone:	
Witness:	