

HOBBS OCD

NOV 20 2019

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name LEGACY RESERVES OPERATING LP	*API Number 30-025-24819
Property Name SKELLY PENROSE A UNIT	Well No. 65

2. Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
K	33	22S	37E		1330	S	1330	W	LEA

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJ	INJECTOR SWD	☒ OIL	PRODUCER GAS	DATE 11-18-19
------------------	-------------------------------------	----------------	-------------------------------------	-----	-----------------	--------------------------------------	-----------------	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	6			4	40
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Dustin Reeder</i>	OIL CONSERVATION DIVISION
Printed name: DUSTIN REEDER	Entered into RBDMS
Title: PRODUCTION TECH	Re-test <i>X</i>
E-mail Address:	
Date: 11-18-19	
Phone:	
Witness:	