

HOBBS OCD

NOV 20 2019

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name LEGACY RESERVES OPERATING LP	API Number 30-025-33786
Property Name SKELLY PENROSE A UNIT	Well No. 84

7. Surface Location

UL - Lot I	Section 04	Township 23S	Range 37E	Feet from 2637	N/S Line S	Feet From 92	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD NO	PRODUCER OIL	GAS 11-18-19	DATE
-------------------------	-----------	-----------------------	-----------	------------------------	------------------	------------------------	------------------------	------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			28	35
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid injected for waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Dustin Reeder</i>	OIL CONSERVATION DIVISION
Printed name: DUSTIN REEDER	Entered into RBDMS
Title: PRODUCTION TECH	Re-test <i>X 7</i>
E-mail Address:	
Date: <i>11-18-19</i>	
Phone:	
Witness:	