

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0730

HOBBS OGD

NOV 20 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name LEGACY RESERVES OPERATING LP	API Number 30-025-34016
Property Name SKELLY PENROSE A UNIT	Well No. 87

Surface Location

UL - Lot O	Section 03	Township 23S	Range 37E	Feet from 1190	N/S Line S	Feet From 1531	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJ	INJECTOR SWD	☒ OIL	PRODUCER GAS	DATE 11-18-19
------------------	-------------------------------------	----------------	-------------------------------------	-----	-----------------	--------------------------------------	-----------------	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø			27	35
Flow Characteristics					
Puff	Ø Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Ø Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Ø Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Ø Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Ø Y / N	Y / N	Y / N	Y / N	
Water	Ø Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Dustin Reeder	OIL CONSERVATION DIVISION
Printed name: DUSTIN REEDER	Entered into RBDMS
Title: PRODUCTION TECH	Re-test X7
E-mail Address:	
Date: 11-18-19	
Phone:	
Witness:	