

HOBBS OCD
NOV 07 2019
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Vanguard		API Number 30-025-35084	
Property Name Bimmini 13 ST		Well No. #2	

2. Surface Location

UL - Lot L	Section 13	Township 17S	Range 35E	Feet from 2310	N/S Line S	Feet From 970	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES <input checked="" type="radio"/> NO	SHUT-IN YES <input checked="" type="radio"/> NO	INJ	INJECTOR SWD	PRODUCER <input checked="" type="radio"/> OIL	GAS	DATE 10-22-19
--	--	-----	-----------------	--	-----	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			30	20
Flow Characteristics					
Puff	Y <input checked="" type="radio"/> N	Y / N	Y / N	Y / N	CO2 _____ WTR _____ GAS _____ Type of Fluid Injected for Waterflood if applies
Steady Flow	Y <input checked="" type="radio"/> N	Y / N	Y / N	Y / N	
Surges	Y <input checked="" type="radio"/> N	Y / N	Y / N	Y / N	
Down to nothing	Y <input checked="" type="radio"/> N	Y / N	Y / N	Y / N	
Gas or Oil	Y <input checked="" type="radio"/> N	Y / N	Y / N	Y / N	
Water	Y <input checked="" type="radio"/> N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Harvey H.		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness: Ray P. [Signature]			

INSTRUCTIONS ON BACK OF THIS FORM