

Print

# State Of New Mexico

## Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham  
Governor  
Sarah Cottrell Propst  
Cabinet Secretary  
Todd E. Leahy, JD, PhD  
Deputy Cabinet Secretary

Adrienne Sandoval  
Division Director



### **"Response Required - Deadline Enclosed"**

*Field Inspection Program  
"Preserving the Integrity of Our Environment"*

22-Nov-19

**APACHE CORPORATION**  
303 Veterans Airpark Ln  
#1000  
Midland, TX 79705

### LETTER OF VIOLATION - Field Inspection

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

### ***INSPECTION DETAIL SECTION***

[30-025-05761] NORTH MONUMENT G/SA UNIT #007

OGRID: 873

G-31-19S-37E 1980 FNL 1980 FEL

| Inspection Date | Type Inspection    | Inspector          | Corrective Action Due By | Inspection No. |
|-----------------|--------------------|--------------------|--------------------------|----------------|
| 11/19/2019      | Routine Inspection | [GR] Gary Robinson | 2/17/2020                | iGR1932338348  |

**Violations:****Rule**

19.15.26 Injection

**Comment:**

Operator reported BHT failed, Rule: 19.15.26.11, prod csg had 350 psi, blew down to trickle, but never stopped flowing water, well was shut in.

19.15 Oil and Gas

**Comment:**

Auto Generated Violation - MIT Failure exists.

**Violation**

Detection of Deficient Mechanical  
Integrity

Mechanical Integrity Failure  
Recorded

Print

# State Of New Mexico

## Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham  
Governor  
Sarah Cottrell Propst  
Cabinet Secretary  
Todd E. Leahy, JD, PhD  
Deputy Cabinet Secretary

Adrienne Sandoval  
Division Director



### **"Response Required - Deadline Enclosed"**

*Field Inspection Program  
"Preserving the Integrity of Our Environment"*

22-Nov-19

**APACHE CORPORATION**  
303 Veterans Airpark Ln  
#1000  
Midland, TX 79705

### LETTER OF VIOLATION - Field Inspection

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

### ***INSPECTION DETAIL SECTION***

[30-025-05764] NORTH MONUMENT G/SA UNIT #016

OGRID: 873

P-31-19S-37E 660 FSL 660 FEL

|                                      |  |  |  |  |
|--------------------------------------|--|--|--|--|
| <b>Inspection Date</b><br>11/19/2019 | <b>Type Inspection</b><br>Routine Inspection | <b>Inspector</b><br>[GR] Gary Robinson | <b>Corrective Action Due By</b><br>2/17/2020 | <b>Inspection No.</b><br>iGR1932338905 |
|--------------------------------------|--|--|--|--|

#### **Violations:**

##### **Rule**

19.15.26 Injection

##### **Comment:**

Operator reported BHT failed, Rule: 19.15.26.11, prod csg had 150 psi, blew down to trickle, but would not stop flowing water, well was shut in.

19.15 Oil and Gas

##### **Comment:**


Auto Generated Violation - MIT Failure exits.

##### **Violation**

Detection of Deficient Mechanical Integrity

Mechanical Integrity Failure  
Recorded

**EMNRD  
OIL CONSERVATION DIVISION  
1625 N FRENCH DRIVE  
HOBBS NM 88240**



**NEOPOST  
FIRST-CLASS MAIL  
\$000.50<sup>0</sup>  
11/22/2019 ZIP 88240  
042L14818194**

**US POSTAGE**

**APACHE COORATION  
303 VETERANS AIRPARK LN  
# 1000  
MIDLAND, TX, 79705**