

HOBBS OGD

DEC 09 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED	Operator Name <i>Fulfer & Cattle Co LLC</i>	API Number <i>30-025-26490</i>
	Property Name <i>Kimmy K</i>	Well No. <i>2</i>

1. Surface Location

UL - Lot <i>F</i>	Section <i>29</i>	Township <i>24S</i>	Range <i>37E</i>	Feet from <i>2310</i>	N/S Line <i>N</i>	Feet From <i>1650</i>	E/W Line <i>W</i>	County <i>Lea</i>
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL ☒ YES ☒ NO	SHUT-IN ☒ YES ☐ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE <i>11/20/2019</i>
---	--	--	---	---------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure					
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Failed MIT - Operator conceded failure, hole in csg above packer as per Mike. Well is shut in.

Signature: <i>Mike Dennis</i>	OIL CONSERVATION DIVISION	
Printed name: <i>Mike DENNIS</i>	Entered into RBDMS	
Title: <i>Operations Mgr.</i>	Re-test	
E-mail Address: <i>MDENNIS30829@gmail.com</i>		
Date: <i>11/20/2019</i>	Phone: <i>4329401890</i>	
Witness: <i>Barry Holman</i>		

INSTRUCTIONS ON BACK OF THIS FORM