

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp		API Number 30-025-10420	
Property Name Eugene Woods		Well No. 5	

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
B	22	22S	37E	589	N	2051	E	Lea

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJECTOR	SWD	OIL	PRODUCER GAS	DATE 12-4-19
------------------	-----------	----------------	-----------	-----------------	-----	------------	-----------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	N/A	N/A	35	50
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Craig Coombes		OIL CONSERVATION DIVISION	
Printed name: Craig Coombes		Entered into RBDMS	
Title: Tech		Re-test	
E-mail Address: Craig.Coombes@apachecorp.com			
Date: 12-4-19	Phone: 575-513-5636		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM