

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MIDLAND OPERATING, INC		API Number 30-025-11246
Property Name LANGLIE MATTIX WOOLWORTH UNIT		Well No. 504

Surface Location

UL - Lot F	Section 27	Township 24S	Range 37E	Feet from 1980	N/S Line N	Feet From 1980	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES X NO	SHUT-IN YES X NO	INJECTOR INJ X SWD	PRODUCER OIL GAS	DATE 8-23-19
------------------------------	----------------------------	------------------------------	---------------------	------------------------

?

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	10/A	0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR X
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	N / N	N / N	Y / N	N / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

MTT
T/A

Failed T/A test - Rule: 19.15.26.11
Started to load prod. csg. - pumped 14.4
BBL & well went on HOBBS OCD

DEC 16 2019

RECEIVED

Signature:		OIL CONSERVATION DIVISION
Printed name: Vivtor Sirgo		Entered into RBDMS
Title: Operator		Re-test
E-mail Address: Vjsirgo@sbcglobal.net		
Date:	Phone: 432-638-5551	
Witness: <i>Darryl Robinson</i>		