

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MIDLAND OPERATING, INC		API Number 30-025-11337
Property Name LANGLIE MATTIX WOOLWORTH UNIT		Well No. 804

1. Surface Location

UL - Lot D	Section 33	Township 24S	Range 37E	Feet from 990	N/S Line N	Feet From 990	E/W Line W	County LEA
---------------	---------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR INJ ☒ SWD	PRODUCER OIL GAS	DATE 8-22-19
---	---	---	---------------------	-----------------

Not T/A

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	250
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	Y / ☒ N	CO2 —
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS —
Down to nothing	☒ Y / N	Y / N	Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

T/A Started to load well - pumped 26 BBLs + started to loose press.
Failed T/A MIT Rule: 19.15.26.11
Well is disconnected, but still has prod. assy. in hole.?

Signature:		OIL CONSERVATION DIVISION
Printed name: Vivtor Sirgo		Entered into RBDMS
Title: Operator		Re-test
E-mail Address: Vjsirgo@sbcglobal.net		
Date:	Phone: 432-638-5551	
Witness: Guy Robinson		