

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MIDLAND OPERATING, INC		API Number 30-025-23112
Property Name LANGLIE MATTIX WOOLWORTH UNIT		Well No. 204

2. Surface Location

UL - Lot M	Section 28	Township 24S	Range 37E	Feet from 330	N/S Line S	Feet From 330	E/W Line W	County LEA
---------------	---------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

TA'D WELL YES X NO	SHUT-IN YES X NO	INJECTOR INJ X SWD	PRODUCER OIL GAS	DATE 8-22-19
-----------------------	---------------------	-----------------------	---------------------	-----------------

DOT T/A
Hooked up

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	VAC	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

T/A Started to load well - pumped 3 BBLs +
Surface csg. started blow gas.
Failed MIT Well is hooked up + ready
to inject.

Signature:		OIL CONSERVATION DIVISION
Printed name: Vivtor Sirgo		Entered into RBDMS
Title: Operator		Re-test
E-mail Address: Vjsirgo@sbcglobal.net		
Date:	Phone: 432-638-5551	
Witness: <i>Samy Robinson</i>		