

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Jilpetco		API Number 30-025-25241	
Property Name SANTA FE		Well No. #2	

1. Surface Location

UL - Lot D	Section 35	Township 10S	Range 36E	Feet from 660	N/S Line N	Feet From 660	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJ INJ	INJECTOR ☒ SWD	OIL OIL	PRODUCER GAS	DATE 12-20-19
------------------	-------------------------------------	----------------	-------------------------------------	------------	--	------------	-----------------	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	cemented		0	VAC
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness: Greg Robinson			

INSTRUCTIONS ON BACK OF THIS FORM