

HOBBS OCD

DEC 31 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>McDONNOLD Operating</i>		API Number <i>30-025-11154</i>	
Property Name <i>Largie Jack</i>		Well No. <i># 12</i>	

Surface Location

UL - Lot <i>I</i>	Section <i>20</i>	Township <i>24S</i>	Range <i>37E</i>	Feet from	NS Line	Feet From	E/W Line	County <i>Lea</i>
----------------------	----------------------	------------------------	---------------------	-----------	---------	-----------	----------	----------------------

Well Status

TA'D WELL YES	☒ NO	☒ YES	SHUT-IN ☒	INJECTOR ☒ INT	SWD	PRODUCER OIL	GAS	DATE <i>8/30/19</i>
------------------	-------------------------------------	--------------------------------------	---	--	-----	-----------------	-----	------------------------

OBSERVED DATA


	(A)Surface	(B)Intern(1)	(C)Intern(2)	(D)Prod Cng	(E)Tubing
Pressure					
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

*MIT
Parker Energy*

Signature:		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone:	
Witness:		

INSTRUCTIONS ON BACK OF THIS FORM



HOBBS OCD

DEC 31 2019

RECEIVED