

NOON
1
2
3
4
5
6 P.M.
7
8
9
10
11
MIDNIGHT
1
2
3
4
5
6 A.M.
7
8
9
10
11
Start
BR 2221
8-29-15
GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

District I
1625 N French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

JAN 06 2020

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name	API Number
Pride Energy	
Property Name	**Well No**
South 4 Lakes	8

Surface Location

Ul. - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
NE NE	2	12S	34E						

Well Status

TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
YES (NO)	YES (NO)	INJ (SWD)	(OIL) GAS	8-29-19

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure					
Flow Characteristics					CO2
Puff	(Y) / N	Y / (N)	(Y) / N	(Y) / N	WTR ✓
Steady Flow	Y / (N)	Y / (N)	Y / (N)	Y / (N)	GAS
Surges	Y / (N)	Y / (N)	Y / (N)	Y / (N)	Type of Fluid Injected for Waterflood if applies
Down to nothing	(Y) / N	(Y) / N	(Y) / N	Y / (N)	
Gas or Oil	Y / (N)	Y / (N)	Y / (N)	Y / (N)	
Water	(Y) / N	Y / (N)	(Y) / N	Y / (N)	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature		OIL CONSERVATION DIVISION
Printed name:	Clayton Ferguson	Entered into RBDMS
Title	Pumper	Re-test
E-mail Address:		
Date:	Phone 575-760-0646	
	Witness.	

INSTRUCTIONS ON BACK OF THIS FORM