

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

Operator Name

API Number

ConocoPhillips Company

3002534834

HOBBS CCD

Well Name

MAR 30 2020

Well No

East Vacuum GB-SA Unit 3127

397

BEE North

RECEIVED

Surface Location

UL - Lot	SEC	Tnsp	Range	Feet From	N/S Line	Feet From	E/W Line	County
J	31	17S	35E	1885	S	2630	E	LEA

Well Status

TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☐ NO ☒	YES ☐ NO ☒	INJ ☐ SWD ☒	GAS ☐ OIL ☒	2-27-20

OBSERVED DATA

	(A)Surface	(B)Interm (1)	(C)Interm (2)	(D) Prod Csg	(E)Tubing
Pressure	Ø	N/A	N/A	51	671
Flow Characteristics					CO2___
Puff	Y / ☒ N	Y / N	Y / N	☒ Y / N	WTR___
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS___
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Down to Nothing	☒ Y / N	Y / N	Y / N	☒ Y / N	
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks- Please state for each string (A,B,C,D) pertinent information regarding bleed down or continuous build up if applies.

Plunger Lift with packer downhole

Signature: B. Hunter North	OIL CONSERVATION DIVISION
Print name: B. Hunter North	Entered in RBDMS
Title: MSO	Re-test
E-mail Address: Hunter.North@contractor.conocoPhillips.com	
Date: 2-27-20	
Phone: 575-704-12032	
Witness:	