

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

Operator Name		API Number
ConocoPhillips Company HOBBS OCD		3002542115
Well Name		Well No
East Vacuum GB-SA Unit 3332 RECEIVED		519
BEE North		

Surface Location

UL - Lot	SEC	Tnsp	Range	Feet From	N/S Line	Feet From	E/W Line	County
M	33	17S	35E	1039	S	819	W	LEA

Well Status

TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
YES	YES	INJ	GAS	3-3-20
☒ NO	☒ NO	☒ OIL		

OBSERVED DATA

	(A)Surface	(B)Interm (1)	(C)Interm (2)	(D) Prod Csg	(E)Tubing
Pressure	170	N/A	N/A	76	134
Flow Characteristics					CO2
Puff	Y / ☒ N	Y / N	Y / N	Y / N	WTR
Steady Flow	☒ Y / N	Y / N	Y / N	Y / N	GAS
Surges	Y / ☒ N	Y / N	Y / N	Y / N	
Down to Nothing	Y / ☒ N	Y / N	Y / N	Y / N	
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / N	
Water	Y / ☒ N	Y / N	Y / N	Y / N	

Remarks- Please state for each string (A,B,C,D) pertinent information regarding bleed down or continuous build up if applies.

3-3-20 Surface casing bled to ^{nearly} zero in 30 sec.

3-4-20 surface casing showed 160 psi

Failed BHT Well was shut in

Signature: <i>B. Hunter North</i>		OIL CONSERVATION DIVISION
Print name: <i>B. Hunter North</i>		Entered in RBDMS
Title: <i>MSO</i>		Re-test <i>4-6-20 Need to send letter</i>
E-mail Address: <i>Hunter.North@contractor.conocophillips.com</i>		
Date: <i>3-4-20</i>	Phone: <i>575-704-6032</i>	
Witness: <i>Darryl Robinson</i>		