

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

Operator Name ConocoPhillips Company	API Number 3002538982
Well Name MCA UNIT	Well No 414W
BEW ☐	

Surface Location

UL - Lot	SEC	Tnsp	Range	Feet From	N/S Line	Feet From	E/W Line	County
O	27	17S	32E	660	S	2630	E	LEA

Well Status

TA'D WELL YES / NO	SHUT-IN YES / NO	INJECTOR (INJ) SWD	PRODUCER OIL / GAS	DATE 3.31.20
-----------------------	---------------------	-----------------------	-----------------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Csg	(E) Tubing
Pressure	O	NA	NA	53 PSI	2101 PSI
Flow Characteristics					CO2
Puff	Y / N	Y / N	Y / N	Y / N	WTR ✓
Steady Flow	Y / N	Y / N	Y / N	Y / N	GAS
Surges	Y / N	Y / N	Y / N	Y / N	
Down to Nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks- Please state for each string (A,B,C,D) pertinent information regarding bleed down or continuous build up if applies.

I will check this well again through-out the month on the surface valve accumulated some water not seen it is from the rain so it check daily !!!

Signature: <i>Dominic Moreno</i>	OIL CONSERVATION DIVISION
Print name: Dominic Moreno	Entered in RBDMS
Title: MSO	Re-test
E-mail Address: Dominic.Moreno@CPL.com	
Date: 3-31-20	Phone: 575-659-9685
Witness: Will White	