

HOBBS

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

APR 22 2020

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Cross Timbers Energy, LLC	* API Number 30-025-26668
Property Name South East Matjamar Grayburg San Andres Unit	Well No. 145

Surface Location

UL - Lot 0	Section 30	Township 17S	Range 33E	Feet from 990	N/S Line FSL	Feet From 1650	E/W Line FEL	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D Well YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ SWD	PRODUCER OIL ☒ GAS	DATE 3-5-20
--	--	--	--	-----------------------

OBSERVED DATA

	(A) Surf-Interm	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	n/a	n/a	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☒
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☒
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

POST WORKOVER following failed MIT. TBG psi @ 0
due to workover.
SEE CHART - START 520# end 510# 32 min
#1000

M&S #2 CAL DATE 2-27-20

Signature: KB	OIL CONSERVATION DIVISION
Printed name: Kevin Bennett	Entered into RBDMS
Title:	Re-test X
E-mail Address:	
Date: 3-5-20	Phone: 575-513-8156
Witness:	

HOBBS 000

APR 22 2020

RECEIVED

