

HOBBS OCD

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

MAY 01 2020

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Maverick Resources		* APT Number 30-025-08651	
Property Name Cone Talmat Yates Pool Unit		Well No. 6002	

1 Surface Location									
UL - Lot J	Section 24	Township 22S	Range 35 E	Feet from	NS Line	Feet from	E/W Line	County Lea	

Well Status		DATE 4-3-2020	
TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒	PRODUCER OIL ☐ GAS ☐

OBSERVED DATA

	(A) Surface	(B) Interval 1	(C) Interval 2	(D) Prod Case	(E) Tubing
Pressure	0			0	900
Flow Characteristics					
Full	Y/N ☒	Y/N	Y/N	Y/N ☒	CO2 ☐
Steady Flow	Y/N ☒	Y/N	Y/N	Y/N ☒	WTR ☒
Surges	Y/N ☒	Y/N	Y/N	Y/N ☒	GAS ☐
Down to nothing	Y/N ☒	Y/N	Y/N	Y/N ☒	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N ☒	Y/N	Y/N	Y/N ☒	
Water	Y/N ☒	Y/N	Y/N	Y/N ☒	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: N Lee		OIL CONSERVATION DIVISION	
Printed name: Nicole Lee		Entered into RBDMS	
Title: Regulatory Compliance Tech		Re-test	
E-mail Address:			
Date: 4/28/2020	Phone: 713-937-8050		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM