

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

MAY 01 2020

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Maverick Resources	* API Number 30-025-08664
Property Name Cone Talmat. Yates Pool Unit	Well No. 702

* Surface Location

UL - Lot B	Section 25	Township 22S	Range 3SE	Feet from 660	NS Line N.	Feet from 1980	E/W Line E.	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	-----------------------	----------------------

Well Status

TA'D WELL YES <input type="radio"/> NO <input checked="" type="radio"/>	SHUT-IN YES <input type="radio"/> NO <input checked="" type="radio"/>	INJECTOR <input checked="" type="radio"/> INJ	SWD	OIL	PRODUCER GAS	DATE 4-3-2020
--	--	--	-----	-----	-----------------	-------------------------

OBSERVED DATA

	(A) Surface	(B) Interval 1	(C) Interval 2	(D) Prod. Cons.	(E) Tubing
Pressure	0	0		0	900
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 <input type="checkbox"/>
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR <input checked="" type="checkbox"/>
Surges	Y/N	Y/N	Y/N	Y/N	GAS <input type="checkbox"/>
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applicable.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Nicole	OIL CONSERVATION DIVISION
Printed name: Nicole Lee	Entered into RBDMS
Title: Regulatory Compliance Tech	Re-test
E-mail Address:	
Date: 4/28/2020	
Phone: 713-437-8050	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM