

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

MAY 07 2020

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>Chevron USA Inc.</i>		API Number <i>30-025-35212</i>
Property Name CENTRAL VACUUM UNIT		Well No. <i># 173</i>

2. Surface Location

UL - Lot <i>H</i>	Section <i>36</i>	Township <i>17S</i>	Range <i>34E</i>	Feet from <i>2500</i>	N/S Line <i>N</i>	Feet From <i>660</i>	E/W Line <i>E</i>	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	---------------

Well Status

TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ INJ SWD	PRODUCER OIL ☐ GAS ☐	DATE <i>3-11-20</i>
--	--	---	---	------------------------

OBSERVED DATA

	(A) Surf-Interm	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	<i>0</i>			<i>220</i>	<i>1200</i>
Flow Characteristics					
Puff	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	CO2 _____
Steady Flow	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☒ N	WTR _____
Surges	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☒ N	GAS _____
Down to nothing	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	If applicable type
Gas or Oil	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☐ Y ☒ N	fluid injected for
Water	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

*MIT - PRODUCTION CASING HAD FLUID, BLEW TO TRUCK, TO ZERO
IN 5 MIN.*

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: <i>Eloy Carmena</i>	Entered into RBDMS
Title: <i>SSPS</i>	Re-test <i>[Signature]</i>
E-mail Address: <i>Ecarmena@Chevron.com</i>	
Date: <i>3-11-2020</i>	Phone: <i>575-200-16265</i>
Witness: <i>[Signature]</i>	

