

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

Operator Name	API Number
ConocoPhillips Company	3002530437

Well Name	Well No
Vacuum Glorleta East Unit 01	006

BEE Cardenas

Surface Location

UL - Lot	SEC	Tnsp	Range	Feet From	N/S Line	Feet From	E/W Line	County
O	28	17S	35E	1195	S	2518	E	LEA

Well Status

TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
YES	YES	INJ	GAS	4-1-20
☒ NO	☒ NO	SWD	☒ OIL	

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Csg	(E) Tubing
Pressure	Ø	N/A	N/A	65	71
Flow Characteristics					CO2
Puff	Y / ☒ N	Y / N	Y / N	Y / N	WTR
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / N	GAS
Surges	Y / ☒ N	Y / N	Y / N	Y / N	
Down to Nothing	☒ Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / N	
Water	Y / ☒ N	Y / N	Y / N	Y / N	

Remarks- Please state for each string (A,B,C,D) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Alex Cardenas</i>	OIL CONSERVATION DIVISION
Print name: Alex Cardenas	Entered in RBDMS
Title: MSO	Re-test
E-mail Address: Alex.R.Cardenas@conocophillips.com	
Date: 4-1-20	Phone: 575-242-2964
Witness:	