<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

## HOBBS OCD

## State of New Mexico

MAY 2 7 2020

RECEIVED

<b>Energy, Minerals and Natural Resources Department</b>
Oil Conservation Division Hobbs District Office

**BRADENHEAD TEST REPORT** 

	PROVID	ENCE ENER	Operate GY SERVICE		<sup>3</sup> API Number 30-025-32112						
Property Name SKELLY PENROSE B UNIT								ı		Well No. 71	
					7. Surface Locat	ion					
UL - Lot	Section	Township	Range	1	T T		Line	ine Feet From		County	
K	5	23\$	37E	.	1420	so	UTH	2614	WEST	LEA	
					Well Status	S					
Ta' D Well			SHUT-IN No		INJECTOR			PRODUCING Oil		DATE 05/21/2020	
	No	i									
	OPI	EN BRADEN	HEAD AND IN	NTERMED	IATE TO ATMOSPHI		/IDUALL'	Y FOR 15 MINU	TES EACH		
f bradenhead	l flowed wa	ter, check all	of the descripti	ons that ap	OBSERVED DA <u>ply:</u>	ATA .					
		(A)Su	ırf-Interm	(B)Inte	(B)Interm(1)-Interm(2)		(C)Interm-Prod		rod Csng	(E)Tubing	
Pressure			N/A						20	20	
Flow Chara	<u>cteristics</u>										
Puf	ſ		Y/N		Y / N		Y / N		Y / N		
Steady Flow			Y/N		Y / N		Y / N		Y - N		
Surges			Y / N		Y / N	Y / N			Y - N		
Down to nothing			Y / N		Y / N		Y / N		Y / N		
Gas or Oil			Y/N		Y / N	Y / N			Y / N		
Water			Y/N		Y / N	Y / N			Y / N		
If bradenhead	l flowed we	ter check all	of the descripti	one that an	nlw•						
CLEAR			rheck all of the description FRESH		SALTY		SULFUR		BLACK		
			,		L		<u>.                                    </u>				
Remarks: Cemented to S	Surface.										
Signature		C.3	>~K	<b></b>				OIL CO	NSERVATIO	ON DIVISION	
Signature: Printed name	e: C. DALI		>~K					OIL CO		ON DIVISION	
			>mK	<b></b>						ON DIVISION	
Printed name	SIDENT	EKELTON	Sw. K	<u></u>				Entered into R		ON DIVISION	

Witness: