

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Penrock Oil Corp.	API Number 30-025-07956
Property Name East Hobbs San Andres Unit	Well No. 307

Surface Location								
UL - Lot J	Section 30	Township 18S	Range 39E	Feet from 2345	N/S Line S	Feet From 1635	E/W Line E	County LEA

Well Status				DATE	
TA'D WELL YES	YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	5-9-2020

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	0
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	0 / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Back on track
ok'd by Paul 10/29/19

HOBBS OCD
JUN 02 2021
RECEIVED

Signature: Dillon Salas	OIL CONSERVATION DIVISION
Printed name: Dillon Salas	Entered into RBDMS
Title: Production Engineer	Re-test
E-mail Address: dillon@penrockoil.com	
Date: 6-02-2020	Phone: 575-492-1236
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM