

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Penrock Oil Corp	API Number 30-025-07958
Property Name East Hobbs San Andres Unit	Well No. 709

Surface Location									
UL - Lot P	Section 30	Township 18S	Range 39E		Feet from 660	N/S Line S	Feet From 660	E/W Line E	County LEA

Well Status						
TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 5-9-2020

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csong	(E)Tubing
Pressure	0			0	20
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood If
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

HOBBS OCD

JUN 02 2020

RECEIVED

Signature: <i>Dillon Salas</i>	OIL CONSERVATION DIVISION
Printed name: Dillon Salas	Entered into RBDMS
Title: Production Engineer	Re-test
E-mail Address: dillon@penrockoil.com	
Date: 5-02-2020	Phone: 575-492-1236
	Witness:

INSTRUCTIONS ON BACK OF THIS FORM