

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Penrock Oil Corp	API Number 30-025-34013
Property Name East Hobbs San Andres Unit	Well No. 611

Surface Location									
UL - Lot M	Section 29	Township 18S	Range 39E		Feet from 1310	N/S Line S	Feet From 330	E/W Line W	County LEA

Well Status					
TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR INJ ☒	SWD ☒	PRODUCER GAS ☒	DATE 5-4-2020

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	20
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	0 / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

HOBBS OCD

JUN 02 2020

RECEIVED

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dillon Salas	Entered into RBDMS
Title: Production Engineer	Re-test
E-mail Address: dillon@penrockoil.com	
Date: 6-02-2020	
Phone: 575-492-1236	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM