

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Penrock Oil Corp.	API Number 30-025-34513
Property Name East Hobbs San Andres Unit	Well No. 507

Surface Location									
UL - Lot J	Section 30	Township 18S	Range 39E		Feet from 1650	N/S Line S	Feet From 1650	E/W Line E	County LEA

Well Status									
YES	TA'D WELL ☒	YES	SHUT-IN ☒	INJ	INJECTOR ☒	SWD	PRODUCER ☒	GAS	DATE 5-9-2020

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			5	20
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

HOBBS OCD
JUN 02 2020
RECEIVED

Signature: <i>Dillon Salas</i>	OIL CONSERVATION DIVISION
Printed name: Dillon Salas	Entered into RBDMS
Title: Production Engineer	Re-test
E-mail Address: dillon@penrockoil.com	
Date: 6-02-2020	Phone: 575-492-1236
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM