

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Penrock Oil Corp.		API Number 30-025-36832	
Property Name East Hobbs San Andres Unit		Well No. 505	

Surface Location									
UL - Lot 5	Section 30	Township 18S	Range 39E		Feet from 1720	N/S Line 5	Feet From 2340	E/W Line E	County LEA

Well Status					DATE	
TA'D WELL ☒ YES NO	SHUT-IN ☒ YES NO	INJECTOR ☐ INJ ☐ SWD	PRODUCER ☒ OIL ☐ GAS	5-4-2020		

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	0
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR. —
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	0 / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

HOBBS OCD
JUN 02 2020
RECEIVED

Signature: <i>Dillon Salas</i>		OIL CONSERVATION DIVISION	
Printed name: Dillon Salas		Entered into RBDMS	
Title: Production Engineer		Re-test	
E-mail Address: dillon@penrockoil.com			
Date: 6-02-2020	Phone: 575-492-1236		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM