

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Penroc Oil Corp.	*API Number 30-025-36896
Property Name East Hobbs San Andres Unit	Well No. 308

Surface Location									
UL - Lot I	Section 30	Township 18S	Range 39E		Feet from 2494	N/S Line S	Feet From 870	E/W Line E	County LEA

Well Status									
TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJECTOR INJ	SWD	☒ OIL	PRODUCER GAS	DATE 5-9-2020	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	20
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

HOBBS OCD
JUN 02 2020
RECEIVED

Signature: <i>Dillon Salas</i>	OIL CONSERVATION DIVISION
Printed name: Dillon Salas	Entered into RBDMS
Title: Production Engineer	Re-test
E-mail Address: dillon@penrocoil.com	
Date: 5-02-2020	
Phone: 575-492-1236	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM