

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name DKD		API Number 30-005-20809	
Property Name Griffin		Well No. #4	

1. Surface Location

UL - Lot A	Section 10	Township 8S	Range 32E	Feet from 660	N/S Line N	Feet From 660	E/W Line E	County Chaves
----------------------	----------------------	-----------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	-------------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJ INJECTOR INJ ☐ SWD ☒	PRODUCER OIL ☐ GAS ☐	DATE 5-12-20
--	--	--	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	VAC.
Flow Characteristics					
Puff	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	CO2 ...
Steady Flow	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	WTR ☒
Surges	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	GAS ...
Down to nothing	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	Type of Fluid
Gas or Oil	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	Injected for
Water	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

~~operator Reported Bldg - ok~~

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness: <i>Greg Griffin</i>			

INSTRUCTIONS ON BACK OF THIS FORM