

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA		API Number 30-025-38216	
Property Name Keller 11 State		Well No. 001Y	

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	NS Line	Feet From	E/W Line	County
E	11	23S	34E	1890	North	330	West	LEA


Well Status

☒ YES	TA'D WELL	NO	YES	SHUT-IN	NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 4-21-20
---	-----------	----	-----	---------	----	-----	----------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	15	10	10	0	
Flow Characteristics					
Puff	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	CO2 WTR GAS Type of fluid Injunct for Waterflood if applies
Steady Flow	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	
Surges	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	
Down to nothing	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	
Gas or Oil	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	
Water	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: _____		OIL CONSERVATION DIVISION	
Printed name: Clarence Fite		Entered into RBDMS	
Title: ALCR		Re-test	
E-mail Address: C.Fite@chevron.com			
Date: 4-21-2020 Phone: 575-390-9084			
Witness			

INSTRUCTIONS ON BACK OF THIS FORM