

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name XTO Energy, Inc	API Number 30-025-28924
Property Name Seven Rivers Queen Waterflood, North	Well No. 11

2. Surface Location

UL - Lot G	Section 4	Township 22S	Range 36E	Feet from 2623	N/S Line North	Feet From 2636	E/W Line East	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	DATE 4-9-2020
------------------	----------------	------------------------	-----------------	------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0	N/A	0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Kevin Mark Burt</i>	OIL CONSERVATION DIVISION
Printed name: Kevin Mark Burt	Entered into RBDMS
Title: Lease Operator	Re-test <i>[Signature]</i>
E-mail Address: kevin-burt@xtoenergy.com	
Date: 4-9-2020	
Phone: 575-441-1639	
Witness:	