

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name XTO Energy, Inc	API Number 30-025-28926
Property Name Seven Rivers Queen Waterflood, North	Well No. 13

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
K	4	22S	36E	1325	South	1330	West	Lea

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ INJ ☐ SWD	PRODUCER OIL ☐ GAS ☐	DATE 4-9-2020
--	--	--	---	------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Kevin Mark Burt</i>	OIL CONSERVATION DIVISION	
Printed name: <i>Kevin Mark Burt</i>	Entered into RBDMS	
Title: <i>Lease Operator</i>	Re-test <i>[Signature]</i>	
E-mail Address: <i>Kevin-burt@xtoenergy.com</i>		
Date: <i>4-9-2020</i>	Phone: <i>575-441-1639</i>	
Witness:		