

HOBBS OCD

JUL 30 2020

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>Apache Corp</i>	API Number <i>30-025-09318</i>
Property Name <i>NUGSAU</i>	Well No. <i>001 (401)</i>

Surface Location

UL Lot <i>A</i>	Section <i>24</i>	Township <i>19S</i>	Range <i>30E</i>	Feet from <i>990</i>	NS Line <i>N</i>	Feet from <i>330</i>	E/W Line <i>E</i>	County <i>Lea</i>
--------------------	----------------------	------------------------	---------------------	-------------------------	---------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJ ☒	SWD	OIL	PRODUCER	GAS	DATE <i>5/30/20</i>
--	--	--------------------------------------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Cmg	(E) Tubing
Pressure	<i>11A</i>		<i>0</i>	<i>0</i>	<i>740</i>
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 WTR ☒ GAS ☐ Type of fluid injected for Waterflood if applies
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature <i>Roug Mathews</i>	OIL CONSERVATION DIVISION
Printed name <i>Roug Mathews</i>	Entered into RBDMS
Title <i>Inspector II</i>	Re-test
E-mail Address <i>doug.mathews@apachecorp.com</i>	
Date <i>5/30/20</i>	
Phone <i>575-631-7713</i>	
Witness	

INSTRUCTIONS ON BACK OF THIS FORM