

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 07 2020

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corp.		API Number 3002506477.0000	
Property Name EAST BLINE bay Windland Unit		Well No. 12	

Surface Location							
UL - Lot	Section	Township	Range	East from	N/S Line	Feet from	County
	11	21	37				LEA

Well Status							
TA'D WELL	YES	NO	SHUT-IN	YES	NO	INJECTOR	SWD
						PRODUCER	GAS
						DATE	4-27-20

OBSERVED DATA

	(A)Surface	(B)Internal	(C)Interm	(D)Prod Cms	(E)Tubing
Pressure	2	2		25	1212
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 WTR ☒ GAS Type of fluid logged for wearhead if applies
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature Albert Rodriguez		OIL CONSERVATION DIVISION	
Printed name: ALBERT RODRIGUEZ		Entered into RBDMS	
Title MECHANIC		Re-test	
E-mail Address:			
Date: 4-27-20	Phone: 432-425-2963		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM