

HOBBS OCD

AUG 07 2020

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corp		API Number 30-025-76523	
Property Name EAST BLINEBAY PRINLAND UNIT		Well No. 2	

Surface Location									
UL - Lot	Section	Township	Range		Feet from	NS Line	Feet from	EAV Line	County
	11	21	37						LEA

Well Status												
YES	TA'D WELL	NO	YES	SHUT-IN	NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
												4-27-20

OBSERVED DATA

	(A) Surface	(B) Intermittent	(C) Intermittent	(D) Prod. Cms	(E) Tubing
Pressure	2			25	1212
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☒
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid Inferred for Water/Oil if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature Albert Rodriguez		OIL CONSERVATION DIVISION	
Printed name: Albert Rodriguez		Entered into RBDMS	
Title: Mechanic		Re-test	
E-mail Address:			
Date: 4-27-20	Phone: 432-425-2963		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM